
FIG 1






FIG 3




FIG 4 6a 4a **Cut Thread** Drill -6b 4b Free DIN-Code G G Free DIN-Code -6c 4c. 11c-**Smooth Surfaces** 4d-WAITM (1, 1, 2) WAITM (1, 1, 2) 11d 6d 10